EXCELCHEMEnvironmental Labs

1135 W Sunset Boulevard Suite A Rocklin, CA 95765 Phone# 916-543-4445 Fax# 916-543-4449



ELAP Certificate No.: 2119

03 July 2012

Calvin Yang

RWQC Central Valley

11020 Sun Center Dr. #200

Rancho Cordova, CA 95670

RE: MUN Evaluation

Work order number:1206261

Enclosed are the results of analyses for samples received by the laboratory on 06/26/12 16:38. All Quality Control results are within acceptable limits except where noted as a case narrative. If you have any questions concerning this report, please feel free to contact the laboratory.

Sincerely,

John Somers, Lab Director

RWQC Central Valley Project: MUN Evaluation
11020 Sun Center Dr. #200 Project Number: [none]

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
AWL 120626-07	1206261-01	Water	06/26/12 09:16	06/26/12 16:38
AWL 120626-08	1206261-02	Water	06/26/12 05:00	06/26/12 16:38
AWL 120626-30	1206261-03	Water	06/26/12 07:59	06/26/12 16:38
AWL 120626-31	1206261-04	Water	06/26/12 08:55	06/26/12 16:38
AWL 120626-32	1206261-05	Water	06/26/12 09:16	06/26/12 16:38
AWL 120626-33	1206261-06	Water	06/26/12 09:36	06/26/12 16:38
AWL 120626-34	1206261-07	Water	06/26/12 10:19	06/26/12 16:38
AWL 120626-35	1206261-08	Water	06/26/12 10:48	06/26/12 16:38
AWL 120626-36	1206261-09	Water	06/26/12 15:14	06/26/12 16:38
AWL 120626-40	1206261-10	Water	06/26/12 11:52	06/26/12 16:38
AWL 120626-41	1206261-11	Water	06/26/12 12:12	06/26/12 16:38
AWL 120626-42	1206261-12	Water	06/26/12 12:26	06/26/12 16:38
AWL 120626-43	1206261-13	Water	06/26/12 14:44	06/26/12 16:38
AWL 120626-44	1206261-14	Water	06/26/12 14:10	06/26/12 16:38
AWL 120626-45	1206261-15	Water	06/26/12 14:25	06/26/12 16:38

Excelchem Environmental Lab.

De Down

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-07 1206261-01 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.09	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	0.251	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-08 1206261-02 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.04	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-30 1206261-03 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.07	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-31 1206261-04 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.04	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De som

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-32 1206261-05 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.07	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	0.137	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-33 1206261-06 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.04	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	n .	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-34 1206261-07 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.03	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-35 1206261-08 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.07	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Down

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-36 1206261-09 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.05	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-40 1206261-10 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrite as Nitrogen	ND	0.15	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley

Project:
Project Number:

MUN Evaluation

11020 Sun Center Dr. #200 Rancho Cordova, CA 95670

Project Number: [none]
Project Manager: Calvin Yang

Date Reported: 07/03/12 16:21

AWL 120626-40 1206261-10RE1 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	19.0	1.10	0.20	mg/L	10	AVF0290	06/27/12	06/27/12	EPA 300.0	

Excelchem Environmental Lab.

De Down

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-41 1206261-11 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrite as Nitrogen	ND	0.15	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Down

RWQC Central Valley

Project: Project Number: MUN Evaluation

11020 Sun Center Dr. #200 Rancho Cordova, CA 95670

Project Number: [none]
Project Manager: Calvin Yang

Date Reported: 07/03/12 16:21

AWL 120626-41 1206261-11RE1 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	19.0	1.10	0.20	mg/L	10	AVF0290	06/27/12	06/27/12	EPA 300.0	

Excelchem Environmental Lab.

De Down

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-42 1206261-12 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrite as Nitrogen	0.21	0.15	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley

Project: MUN Evaluation

11020 Sun Center Dr. #200 Rancho Cordova, CA 95670

Project Number: [none]
Project Manager: Calvin Yang

Date Reported: 07/03/12 16:21

AWL 120626-42 1206261-12RE1 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	10.9	0.55	0.10	mg/L	5	AVF0290	06/27/12	06/27/12	EPA 300.0	

Excelchem Environmental Lab.

De som

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-43 1206261-13 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.08	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-44 1206261-14 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.09	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Down

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

AWL 120626-45 1206261-15 (Water)

Analyte	Result	Reporting Limit	MDL	Units	DF	Batch	Date Prepared	Date Analyzed	Method	Notes
Ion Chromatography										
Nitrate as Nitrogen	0.06	0.11	0.02	mg/L	1	AVF0290	06/27/12	06/27/12	EPA 300.0	J
Nitrite as Nitrogen	ND	0.15	0.02	"	1	"	"	"	"	
Wet Chemistry										
MBAS	ND	0.100	0.0600	mg/L	1	AVF0283	06/27/12	06/27/12	SM5540C	

Excelchem Environmental Lab.

De Donn

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200 Project Number: [none] Date Reported:

Rancho Cordova, CA 95670 Project Manager: Calvin Yang 07/03/12 16:21

Ion Chromatography - Quality Control

Analyte	Result	Reporting Limit	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch AVF0290 - EPA 300.0											
Blank (AVF0290-BLK1)					Prepared &	Analyzed:	06/27/12				
Nitrite as Nitrogen	ND	0.15	0.02	mg/L							
Nitrate as Nitrogen	ND	0.11	0.02	"							
LCS (AVF0290-BS1)					Prepared &	Analyzed: (06/27/12				
Nitrite as Nitrogen	2.91	0.15	0.02	mg/L	3.05		95.4	80-120			
Nitrate as Nitrogen	2.17	0.11	0.02	"	2.26		96.0	80-120			
LCS Dup (AVF0290-BSD1)					Prepared &	Analyzed: (06/27/12				
Nitrite as Nitrogen	2.93	0.15	0.02	mg/L	3.05		96.1	80-120	0.687	20	
Nitrate as Nitrogen	2.17	0.11	0.02	"	2.26		95.9	80-120	0.156	20	
Duplicate (AVF0290-DUP1)		Sour	ce: 1206255-	-01	Prepared &	Analyzed: (06/27/12				
Nitrite as Nitrogen	0.29	0.15	0.02	mg/L		0.28			6.06	20	
Nitrate as Nitrogen	0.41	0.11	0.02	"		0.43			3.22	20	
Matrix Spike (AVF0290-MS1)		Sour	ce: 1206261-	-01	Prepared &	Analyzed: (06/28/12				
Nitrite as Nitrogen	3.10	0.15	0.02	mg/L	3.05	ND	102	75-125			
Nitrate as Nitrogen	2.31	0.11	0.02	"	2.26	0.09	98.2	75-125			
Matrix Spike Dup (AVF0290-MSD1)		Sour	ce: 1206261-	-01	Prepared &	Analyzed: (06/28/12				
Nitrite as Nitrogen	3.19	0.15	0.02	mg/L	3.05	ND	105	75-125	2.80	20	
Nitrate as Nitrogen	2.31	0.11	0.02	"	2.26	0.09	98.3	75-125	0.186	20	

Excelchem Environmental Lab.

De Down

RWQC Central Valley Project: MUN Evaluation

11020 Sun Center Dr. #200 Project Number: [none] Date Reported:

Rancho Cordova, CA 95670 Project Manager: Calvin Yang 07/03/12 16:21

Wet Chemistry - Quality Control

Analyte	Result	Reporting Limit	MDL	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch AVF0283 - SM5540C											
Blank (AVF0283-BLK1)					Prepared &	Analyzed: (06/27/12				
MBAS	ND	0.100	0.0600	mg/L							
LCS (AVF0283-BS1)					Prepared &	Analyzed: (06/27/12				
MBAS	0.480	0.100	0.0600	mg/L	0.500		96.0	90-110			
LCS Dup (AVF0283-BSD1)					Prepared &	Analyzed: (06/27/12				
MBAS	0.482	0.100	0.0600	mg/L	0.500		96.4	90-110	0.416	15	

Excelchem Environmental Lab.

De Donn

RWQC Central ValleyProject:MUN Evaluation11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

Notes and Definitions

J Detected but below the Reporting Limit; therefore, result is an estimated concentration (CLP J-Flag).

ND Analyte not detected at reporting limit.

NR Not reported

Analysis Method

EPA 8260, EPA 8021/8015M

EPA 8270, EPA 8081, EPA 8082, EPA 8141, EPA 8015M (extractable)

Metals

TCLP

Not Specified

Prep Method

EPA 5030B

Water - EPA 3510C, Soil- EPA 3550B

Water- 3005A, Soil- 3050B

EPA 1311

Same as Analysis Method

Excelchem Environmental Lab.

De Down

RWQC Central Valley 11020 Sun Center Dr. #200 Rancho Cordova, CA 95670 Project:

MUN Evaluation

Project Number: Project Manager: [none] Calvin Yang Date Reported: 07/03/12 16:21

CHAIN-OF-CUSTODY RECORD AND ANALYSIS REQUEST aladez@waterboards.ca.gov Leticia Valadez, Central Valley Regional Water Quality Control Board Email Address: Page Electronic Data Deliverables Request: ANALYSIS REQUEST Geotracker (slobelity) Bill To: ద **ABTAV** 1135 W. Sunset Blvd. Suite A Rocklin, CA 95765 6/26/12/1638 Central Valley Regional Water Quality 11020 SLASTIC Date Center Drive Suite #200 Environmental Labs Excelchem WL120626-07 ML120626-08 WL120626-30 WL120626-31 WL120626-32 WL120626-33 WV/120626-34 WL120626-35 WL120626-36 WL120626-40 WL120626-41 WL120626-42 WL120626-43 WL120626-44 WL120626-45 Sample ID CA 95670

Excelchem Environmental Lab.

Du Down

RWQC Central ValleyProject:MUN Evaluation11020 Sun Center Dr. #200Project Number:[none]Date Reported:Rancho Cordova, CA 95670Project Manager:Calvin Yang07/03/12 16:21

Sample Transport: ONTRAC UPS USPS Walk-In EXCELCHEM Courier Fed-Ex Other: Transported In Ice Chest Box Hand Describe type of packing materials: Bubble Wrap Foam Packing Peanuts Paper Other: Has chilling process begun? In Samples Received: Chilled to Touch / Ambient Temperature of Samples (°C): Ice Chest Temperature(s) (°C): Section 2 – Bottle/Analysis Info. Did all bottles arrive unbroken and intact? Ice Chest Temperature(s) (°C): Were correct containers used for the tests requested? Ice Chest Temperature of Samples agree with COC? Were correct preservations used for the tests requested? Ice Chest Temperature of Samples agree with COC? Were bubbles present in VOA Vials?: (Volatile Methods Only) Section 3 – Summa/Flow regulator Info. Used Summa#: Cleaning Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Info From Completed Ves No Container Yes No Comments Samples arrived within holding time	
Transported In: Ce Chest Box Hand Describe type of packing materials: Bubble Wrap Foam Packing Peanuts Paper Other: Has chilling process begun? YN Samples Received: Chilled to Touch / Ambient Temperature of Samples (°C):	
Has chilling process begun? N Samples Received: Chilled to Touch / Ambient Temperature of Samples (°C):	t On Ice
Temperature of Samples (°C): Section 2 – Bottle/Analysis Info. Did all bottles arrive unbroken and intact? Did all bottle labels agree with COC? Were correct containers used for the tests requested? Were correct preservations used for the tests requested? Was a sufficient amount of sample sent for tests indicated? Were bubbles present in VOA Vials?: (Volatile Methods Only) Section 3 – Summa/Flow regulator Info. Used Summa#: Unused Summa#: Unused Summa#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Info From Completed Yes No Container Yes No Comme	t On Ice
Section 2 – Bottle/Analysis Info. Did all bottles arrive unbroken and intact? Did all bottle labels agree with COC? Were correct containers used for the tests requested? Were correct preservations used for the tests requested? Was a sufficient amount of sample sent for tests indicated? Were bubbles present in VOA Vials?: (Volatile Methods Only) Section 3 – Summa/Flow regulator Info. Used Summa#: Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Info From Completed Yes No Container Yes No Comme Was COC Received Analysis Requested	
Did all bottles arrive unbroken and intact? Did all bottle labels agree with COC? Were correct containers used for the tests requested? Were correct preservations used for the tests requested? Was a sufficient amount of sample sent for tests indicated? Were bubbles present in VOA Vials?: (Volatile Methods Only) Section 3 — Summa/Flow regulator Info. Used Summa#: Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 — COC Info. Completed Info From Completed Yes No Container Yes No Comme Was COC Received Analysis Requested	
Did all bottles arrive unbroken and intact? Did all bottle labels agree with COC? Were correct containers used for the tests requested? Were correct preservations used for the tests requested? Was a sufficient amount of sample sent for tests indicated? Were bubbles present in VOA Vials?: (Volatile Methods Only) Section 3 – Summa/Flow regulator Info. Used Summa#: Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Yes No Commet Was COC Received Analysis Requested	
Did all bottle labels agree with COC? Were correct containers used for the tests requested? Were correct preservations used for the tests requested? Was a sufficient amount of sample sent for tests indicated? Were bubbles present in VOA Vials?: (Volatile Methods Only) Section 3 — Summa/Flow regulator Info. Used Summa#: Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 — COC Info. Completed Info From Completed Yes No Commet	
Were correct containers used for the tests requested? Were correct preservations used for the tests requested? Was a sufficient amount of sample sent for tests indicated? Were bubbles present in VOA Vials?: (Volatile Methods Only) Section 3 – Summa/Flow regulator Info. Used Summa#: Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Info From Completed Yes No Container Was COC Received Analysis Requested	AL
Were correct preservations used for the tests requested? Was a sufficient amount of sample sent for tests indicated? Were bubbles present in VOA Vials?; (Volatile Methods Only) Section 3 – Summa/Flow regulator Info. Used Summa#: Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Yes No Container Ves No Container Ves No Commet	in ord
Was a sufficient amount of sample sent for tests indicated? Were bubbles present in VOA Vials?: (Volatile Methods Only) Section 3 – Summa/Flow regulator Info. Used Summa#: Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Yes No Container Ves No Container Ves No Commet	NOT
Were bubbles present in VOA Vials?: (Volatile Methods Only) Section 3 – Summa/Flow regulator Info. Used Summa#: Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Info From Completed Yes No Commet Yes No Co	sample
Section 3 – Summa/Flow regulator Info. Used Summa#: Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Info From Completed Yes No Container Yes No Comme Was COC Received Analysis Requested	
Used Summa#: Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Info From Completed Ves No Container Yes No Comme Was COC Received Analysis Requested	
Unused Summa#: Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Info From Completed Ves No Container Yes No Comme Was COC Received Analysis Requested	
Cleaning Summa#: Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Info From Completed Yes No Container Yes No Comme Was COC Received Analysis Requested	
Regulator#: Was there any visual damage to summa canisters or flow regulators? Explain. Section 4 – COC Info. Completed Info From Completed Yes No Container Yes No Comme Was COC Received Analysis Requested	
Section 4 – COC Info. Completed Info From Completed Yes No Container Analysis Requested Was COC Received Analysis Requested	
Section 4 – COC Info. Completed Info From Completed Yes No Container Yes No Comme Was COC Received Analysis Requested X X X X	
Section 4 – COC Info. Completed Completed Completed Yes No Comme Vas No Container Analysis Requested Xes No Comme Xes No Comme	
Section 4 – COC Info. Completed Completed Completed Yes No Comme Vas No Container Analysis Requested Xes No Comme Xes No Comme	
Completed Info From Completed Ves No Container Yes No Common	
Completed Info From Completed Ves No Container Yes No Common	
Was COC Received Analysis Requested Comme	
Was COC Received Analysis Requested	-
	ients
Rush I Al Address/Telephone #	
Time Sampled Any hold times less than 72 hrs Sample ID Client Name	nents
Rush TAT Address/Telephone #	
Section 5 – Comments / Discrepancies	
Was Client notified of disconnection Voc. No. NA. NA.	
Was Client notified of discrepancies: Yes No N/A Notified by:	
Explanations / Comments:	

Excelchem Environmental Lab.